ECQA QUALITY | COMPLIANCE	**Inspection Report**	Conclusion **PASS**

Part 1- Basic Information

Report Number		
Factory	Linyi Cuzi plywood Co.,Limited	
Purchase Order	/	
Item Number	21mm / 24mm / 30mm	
Product Description	PLYWOOD 100% Birch plywood, WBP, Phenolic E1 Glue, 2500x1250mm	
Order Quantity	1596pcs,1376pcs, 2548pcs	
Approval Sample is in Place	☐ Yes ☒ No	
Inspection Type	☐ PPI ☐ DPI ☒ FRI ☐ 1st Re-FRI	
General Inspection Level	Normal Single Plan, Level I☒ , II☐ , III☐	
AQL	Critical: Not Allowed; Major.: 2.5; Minor: 4.0; Sample size:80pcs	
AQL Conformed	☒ Within AQL ☐ Beyond AQL	
Address of Inspection	No.184 Huilongshan Road, Huangdao District	
Date of Inspection	2025.03.11	Arrival & Departure Time：9:00 - 16：00
Inspector	Sky Sun	

Part 2- Total Summary

Inspection Details	Conformed	Not Conformed	Pending	Not applicable	Remark
I. Workmanship	☒	☐	☐	☐	
II. Production Information Verify	☒	☐	☐	☐	
III. Packaging Check	☒	☐	☐	☐	
IV. Date measurement /On-site check	☒	☐	☐	☐	
V. Quantity Check	☒	☐	☐	☐	

CUZI PLY

Part 3-Remark


Remarks for reference:

1. The pallet label is not pasted, the factory said it will be pasted when shipping.

2. Appearance inspection followed standard of CP grade, resulted Pass.

Remark Photo





The pallet label is not pasted, the factory said it will be pasted when shipping.

THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04

ECQA QUALITY | COMPLIANCE	Inspection Report	Conclusion PASS

I. Workmanship

Item No.	Sample size	Defects Description	Location + Size	Defective Classification		
				Critical	Major	Minor
2500*1250*24mm	80	Dirty	/	0	0	1
2500*1250*30mm		Remaining Material Not Removed	/	0	0	1
2500*1250*21mm		No defect found	/	0	0	0
PASS			Defect Found:	0	0	2
			Defect Max. Allowed:	0	5	7

Defect Photo:



Dirty (Minor)



Remaining Material Not Removed (Minor)

II. Production Information Verify

Check Item	Conformed	Not Conformed	Pending	Not Applicable	Remark
1. Product Description、Style、Colour	☐	☐	☐	☒	
2. Check against the approved sample	☐	☐	☐	☒	
3. Instruction Manual check	☐	☐	☐	☒	
4. Product Dimension Measurement	☒	☐	☐	☐	
5. Product Weight Measurement	☒	☐	☐	☐	

Table 1- Product Dimension and Weight Measurement

Product Dimension

Item No.	Specification	Sample		
		Req.	1	2
21mm	2500*1250*21mm	±1.5mm	2500*1250*21.09mm	2500*1250*21.05mm
		Diagonal difference 2mm	1mm	1mm
24mm	2500*1250*24mm	±1.5mm	2500*1250*24.10mm	-
		Diagonal difference 2mm	1mm	-

THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04

30mm	2500*1250*30mm	±1.5mm	2500*1250*30.21mm	2500*1250*30.10mm
		Diagonal difference 2mm	1.5mm	1mm

Product Weight


Item No.	Specification	Requirement	Sample	
			1	2
21mm	-	-	46.5kg	46.6kg
24mm	-	-	50.0kg	-
30mm	-	-	63.5kg	63.6kg

III. Packaging Check

Check Item	Conformed	Not Conformed	Pending	Not Applicable	Remark
1. Method of Packaging Verify	☒	☐	☐	☐	
2. Artwork Documents Verify	☐	☐	☐	☒	
3. Shipping Mark	☐	☐	☐	☒	
4. Packing Quantity	☒	☐	☐	☐	

Method of Packaging:





THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04





Table 2- Product Packaging Information Measurement

Item No.	Master Carton				Inner Box			
	Dimension (cm)		Gross Weight (kg)		Dimension (cm)		Gross Weight (kg)	
	Req.	Finding	Req.	Finding	Req.	Finding	Req.	Finding
2500*1250*21mm	*	251*127*92	*	1773	/	/	/	/
2500*1250*24mm	*	251*127*97	*	1706	/	/	/	/
2500*1250*30mm	*	251*127*91	*	1711	/	/	/	/

Note: Deviations from the requirements shall be highlighted

CUZI PLY

Table 3 - Quantity of Packing

Item Number	Quantity of Export Carton contains (Pcs)		Quantity of Inner Box contains (Pcs)	
	Req.	Finding	Req.	Finding
2500*1250*21mm	1596	1596	/	/
2500*1250*24mm	1376	1376	/	/
2500*1250*30mm	2548	2548	/	/

IV. Data Measurement /On-site check

Test items	Sample size	Requirements	Result	Remark
Moisture testing	2pcs each	5-14%	Pass	6-10%
Size measurement	2pcs each		Pass	

THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04

V. Quantity Check

Check Item	Conformed	Not Conformed	Pending	Not Applicable	Remark
1. Shipment Quantity	☒	☐	☐	☐	
2. Available Quantity	☒	☐	☐	☐	
3. Packing Quantity	☒	☐	☐	☐	

Table 4- Quantity Breakdown and Sampling Status

Purchase Order	Item Number	Order Quantity	Available Quantity	Unfinished Quantity	Sample Size
-	2500*1250*21mm	1596	1596	0	23
-	2500*1250*24mm	1376	1375	1	20
-	2500*1250*30mm	2548	2547	1	37

CUZI PLY

THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04

Annex I - Photo documentation

Storage and Warehouse:






Packaging
1.2500*1250*21mm




THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.

2.2500*1250*24mm





3. 2500*1250*30mm





Product

1.2500*1250*21mm





THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.




2.2500*1250*24mm






THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04

3.2500*1250*30mm






On-site Testing
1.2500*1250*21mm




THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.













THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04














THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.

2.2500*1250*24mm



THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04













THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.





3.2500*1250*30mm









THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.














THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04






Factory gate and sampling




THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.

ECQA QUALITY | COMPLIANCE	Inspection Report	Conclusion PASS






Signature of ECQA Inspector(s)	Sky Sun	ECQA Report Reviewer	Bruce Li
Approved Date	2025.03.12	ECQA Approved	Alex

-- END --

THE RESULTS REFLECT OUR FINDINGS ONSITE INSPECTION AT THAT TIME.THIS REPORT DOES NOT RELIEVE MANUFACTURERS FROM THEIR CONTRACTUAL LIABILITIES OR PREJUDICE CLIENTS' RIGHT FOR COMPENSATION, FOR ANY APPARENT AND/OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER. THIS REPORT DOES NOT EVIDENCE SHIPMENT, WHICH WILL BE SUBJECT TO CLIENT'S DECISION.
ETSC-PSI-DUR-HL-REV04